



## ADECIA SOLUTION: Please Read

### **FIRMWARE**

VXL-16P Speakers

Firmware update of V1.1.0 or later version is required on VXL1-16P to use ADECIA Solution.

### **KNOWN ISSUES**

RM-CR has the known issue below:

When both of two Network ports of RM-CR are in the unconnected status (Corporate Network IP Addresses are 169.254.xxx.xxx), Web GUI of RM-CG via Web GUI of RM-CR will not work correctly. (unable to get the device information of RM-CG and set it up.)

### **Workaround Options:**

- Using an Ethernet cable, please connect one of the Network ports of RM-CR to a free port of SWR2311P-10G that the [Dante/PoE] port of RM-CR is connected to.

OR

- Using RM Device Finder, please directly have access to Web GUI of RM-CG.