



Yamaha CS-700

Firmware Version: 1.1.1

Product Release Notes

Issues resolved and features added in this firmware release:

Summary	Notes
SIP	Internal software support for SIP calling functionality
CLI Command enhancements	Support for SIP, Camera Configuration and control features
Web UI	Extended Web UI for SIP and Camera configuration
Camera performance Improvements	Camera default changes for picture enhancement
Fixed image quality issues with camera initializations	Improvements in camera startup performance
Updated camera image defaults for a better out of box experience	Performance tuning of camera sensor and default settings
Fixed bugs in system firmware found since last release	Quality improvements under QMS

Known issues in this firmware release:

Summary	Notes
On setups using Google Chromebook devices, if the user manipulates the CS-700 touch panel for volume, the volume bar on the Chromebook device will peg to either maximum or minimum.	You can manually adjust volume settings in Chrome OS
Import and export of configuration does not work with the USB API, and with the Service App. Import and export of configuration works properly from the Web UI.	Please use the Web UI program