



Yamaha CS-700
Version: 1.4
Product Release Notes
March 25, 2020

New features and improvements in this release:

Summary	Notes
Certified for Zoom Rooms	CS-700 version 1.4 was certified as Zoom Rooms hardware device
Mic Mute Synchronization with UC Apps	Mic mute button operation and color status synchronize with UC apps. Compatible UC apps: <ul style="list-style-type: none">- Microsoft Skype for Business- Microsoft Teams- Zoom Rooms*- Zoom Meetings* * Zoom Rooms and Zoom Meetings will be supported by their updating in April 2020
Zoom Rooms Camera PTZ Preset Support	Supported Zoom Rooms camera preset feature
Bluetooth device auto-unpair	Added "Bluetooth device auto-unpair" option to allow CS-700 to automatically unpair a linked Bluetooth device when that device disconnects.
System Password	Allowed system password to accept alphanumeric and symbols
Restore Factory Defaults	Added a method to restore factory defaults with pressing and holding "MIC mute" and "Bluetooth" buttons simultaneously on the front panel for 5 seconds
Camera Zoom Ratio	Expanded maximum of camera zoom ratio up to 4x from default
Camera Image Enhancement	Enhanced camera image with <ul style="list-style-type: none">- Added new auto exposure to work based on zoomed image region- Fixed case of over exposure- Improved color accuracy
Audio Quality Enhancement	Enhanced audio quality with <ul style="list-style-type: none">- Improved AEC performance- Improved noise reduction performance
CS-700 Camera Control Application for Windows and macOS	Releasing Camera Control Application to allow end-users controlling the CS-700 camera's Pan, Tilt and Zoom setting

Issues resolved in this release:

Summary	Notes
---------	-------



Security Vulnerabilities	Fixed several SSL/TLS and SSH vulnerabilities that are discovered in prior version
Video Freezing on Chrome OS	Fixed video freezing issue on a variety of devices with Chrome OS

Note for upgrading from Service Application

CS-700 Service Application needs to be version 1.4 to upgrade CS-700 firmware. Please upgrade the Service Application first then upgrade the CS-700 firmware.